




SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location NE 1/4 SE 1/4 Sec 30 Twp 121 Rg 52 Well Owner:County Grant

Please mark well location with an "X"

Name: Kris BronsonAddress: 14862 450th Ave.City, State, Zip: Ortley SD 57256

Comments:

Plugging Completion Date 8/21/2024

CHECK APPROPRIATE BOX

EXISTING WELL ☒	TEST HOLE ☐
Well depth <u>15'</u>	Hole depth _____
Casing material <u>steel</u>	Hole size _____
Casing size(s) <u>1.5"</u>	
Casing condition <u>good</u>	

Describe plugging procedure:

Casing was able to be completely removed. The hole was then filled with bentonite and the top was concreted.

Describe grout or plugging material:

Bentonite + concrete

Type of non-slip plug: _____

This well or test hole was plugged under license # 599 and this report is true and accurate.Drilling firm: Dakota EnvironmentalSignature of Licensed Representative: [Signature]

Signature of Well Owner: _____

Date: 9/6/24

RECEIVED

SEP 09 2024

OFFICE OF
WATER