


## SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location SE  $\frac{1}{4}$  NE  $\frac{1}{4}$  Sec 22 Twp 119N Rg 49W

Well Owner:

County GrantPlease mark well  
location with an "X"Name: Johnson CattleAddress: 15799 474<sup>th</sup> AveCity, State, Zip: Stockholm SD 57264

Comments:

Plugging Completion Date 9-17-2024

## CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 60'Casing material SteelCasing size(s) 4"Casing condition Good

Hole depth \_\_\_\_\_

Hole size \_\_\_\_\_

Describe plugging procedure:

Removed pump + 40' of 1" steel drop pipe  
Tremmie line from bottom to top

Describe grout or plugging material:

3 bags Groutwell DF  
1 bag Neet cement

Type of non-slip plug: \_\_\_\_\_

This well or test hole was plugged under license # 598 and this report is true and accurate.Drilling firm: Kranz Well + Excav LLCSignature of Licensed Representative: Chad King

Signature of Well Owner: \_\_\_\_\_

Date: 9-17-2024

RECEIVED

SEP 25 2024

OFFICE OF  
WATER