


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location NE 1/4 SE 1/4 Sec 30 Twp 121 Rg 52 Well Owner:County GrantPlease mark well
location with an "X"

Name:

Kris Bronson

Address:

14862 450th Ave.

City, State, Zip:

Ortley SD 57256

Comments:

Plugging Completion Date 8/21/2024

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐

Well depth

15'

Casing material

steel

Casing size(s)

1.5"

Casing condition

good

Hole depth

Hole size

Describe plugging procedure:

Casing was able to be completely removed. The hole was then filled with bentonite and the top was concreted.

Describe grout or plugging material:

Bentonite + concrete

Type of non-slip plug: _____

This well or test hole was plugged under license # 599 and this report is true and accurate.

Drilling firm:

Dakota Environmental

Signature of Licensed Representative:

[Signature]

Signature of Well Owner: _____

Date:

9/6/24

RECEIVED

SEP 09 2024

OFFICE OF
WATER

WATER