


2710-2

SD EForm - 1622LD V1

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location NE 1/4 NW 1/4 Sec 29 Twp 37 Rg 33WWell Owner: ~~Oneill~~ Oneill Cattle Co Inc.County BennettName: c/o Rick Oneill

Please mark well location with an "X"

Address: 24381 294th StreetCity, State, Zip: Cody, NE 69211Comments: 605-685-3888Permit # 2710-2Original well Abandoned after well collapsedPlugging Completion Date 6-27-2024

CHECK APPROPRIATE BOX

EXISTING WELL ☒TEST HOLE ☐Well depth 240

Hole depth _____

Casing material PVC SDR26

Hole size _____

Casing size(s) 16"Casing condition Collapsed Below 200'Pump Could Not Be Pulled

Describe plugging procedure:

We filled the well with Clean Gravel Up to 20' below surface.
We filled 20'-5' with Bentonite Holeplug. We cut off casing and pump column at 5' below grade and Glued on 16" PVC Cap

Describe grout or plugging material:

Bentonite 3/8 holeplug 5'-20' Below Surface
Clean Gravel 20'-210'. Casing Collapsed below 210'

Type of non-slip plug: _____

This well or test hole was plugged under license # 377 and this report is true and accurate.Drilling firm: Beck's Well & Irrigation IncSignature of Licensed Representative: [Signature] 10-12-2024Signature of Well Owner: [Signature] presDate: 10-15-24

RECEIVED

OCT 28 2024

OFFICE OF
WATER