


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NE 1/4 SE 1/4 Sec 5 Twp 101-N Rg 49-W
of the 5th meridian Prime
County Minnehaha



Please mark well
location with
an "X"
within the city
limits of the
City of Sioux Falls, S.D.

Well Owner:

Name FSD AirportAddress 2801 Mrs. Jaycee Lane Sioux Falls
S.D.A.K.
57164By Soukup Construction Inc.Plugging completion Date 10-7-25

CHECK APPROPRIATE BOX

EXISTING WELL

☒ Monitor

TEST HOLE

☐

Well depth

37'

Hole depth

Casing material

Iron-steel

Hole size

Casing size(s)

6"

Casing condition

Good

Describe plugging procedure:

Clear holeSWL 15'Pearock 17'-37'Bentonite 12'-17' Tremied InClay-Bentonite 9'-12'cut off 9'Describe grout or plugging material: Bentonite + Clay

Type of non-slip plug:

This well or test hole was plugged under license # 111

And this report is true and accurate.

Drilling firm Lacey Well Drilling Inc.

Signature of Licensed Representative

Jordan Redde Lacey

Signature of Well Owner

Date

11-21-25

RECEIVED

DEC 01 2025

OFFICE OF
WATER