


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT 11-02

Location NW 1/4 NW 1/4 Sec 8 Twp 128N Rg 56WCounty MarshallPlease mark well
location with an "X"45°55'6"N,
97°34'58"WPlugging Completion Date 11-14-25

Well Owner:

Name:

Address:

City, State, Zip: Havana, ND 58043

Comments:

RECEIVED

JAN 20 2026

OFFICE OF
WATER

CHECK APPROPRIATE BOX

EXISTING WELL ☒	TEST HOLE ☐
Well depth <u>186'</u>	Hole depth _____
Casing material <u>PVC</u>	Hole size _____
Casing size(s) <u>4"</u>	
Casing condition <u>good</u>	

Describe plugging procedure:

Tremie line pressure grouted from bottom to top

Describe grout or plugging material:

Grout-Well. 4 bags.

Type of non-slip plug: _____

This well or test hole was plugged under license # 839 and this report is true and accurate.Drilling firm: Wieber Drilling LLCSignature of Licensed Representative: Derek Wieber

Signature of Well Owner: _____

Date: 11-30-25