


SOUTH DAKOTA WATER WELL COMPLETION REPORT

2024

Location NE $\frac{1}{4}$ SE $\frac{1}{4}$ Sec 16 Twp 7E Rg 1S
 County Pennington
 GPS Coordinates
 Lat: _____
 Lon: _____
 Please mark well location with an "X" on section grid
 Well Completion Date 1/20/2026
 Distance from nearest potential pollution source (Septic tank, abandoned well, feed lot, etc.)
 ? 150 ft. from Septic (identify source)



Well Owner: Heather and Tyler Kissner **RECEIVED**
 Business Name: _____
 Address: 13896 Neck Yolk Rd **FEB 17 2026**
 City, State, Zip: Rapid City, SD 57702 **OFFICE OF WATER**

FORMATION	DEPTH	
	FROM	TO
Minnekhata	0.0	35.0
Opeche	35.0	125.0
Minnelusa	125.0	620.0
Madison	620.0	640.0
Madison Fracture 30 gpm	640.0	700.0

PROPOSED USE:
☒ Domestic/Stock ☐ Municipal ☐ Business ☐ Monitoring Well
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Test Hole
☐ Dewatering Well ☐ Geothermal ☐ Other _____

METHOD OF DRILLING: Forward Rotary Air Hammer
CASING DATA: ☒ Steel ☐ Plastic ☐ Other
 If other describe set 640 ft of 5" steel

PIPEWEIGHT	DIAMETER	FROM	TO	HOLE DIAMETER
LB/FT	IN	FT	FT	IN
		0	700	6.88

STATIC WATER LEVEL 450.0 FEET
 If flowing: closed in pressure _____ PSI
 GPM flow 30.0 through _____ Inch pipe
 Controlled by ☐ Valve ☐ Reducers ☐ Other _____
 Reduced flow rate _____ GPM
 Can well be completely shut in? _____

GROUTING DATA:
 Grout Type Portland II No. of Sacks 50 Grout Weight Lb/gal From 640.0 Ft To 0.0 Ft
w/ 2% bent Lb/gal Ft Ft
 Describe grouting procedure Through Casing

WELL TEST DATA:
☒ Pumped Describe: w/ air
☐ Bailed ☒ Air
☐ Other _____
 Pumping Level Below Land Surface
 _____ Ft. After _____ Hrs. pumped _____ GPM
 _____ Ft. After _____ Hrs. pumped _____ GPM
 If pump installed, pump rate: _____ GPM

SCREEN: ☐ Perforated pipe ☐ Manufactured
 Diameter _____ Inches Length _____ Feet
 Material _____
 Slot Size _____ Set From _____ Feet to _____ Feet
 Other information _____

REMARKS

WAS A PACKER OR SEAL USED? ☐ Yes ☒ No
 If so, what material? _____
 Describe packer(s) and location _____

This well was drilled under license # 324
 And this report is true and accurate.
 Drilling firm: Alexander Drilling, Inc
 Signature of License Representative: _____

DISINFECTION: Was well disinfected upon completion?
☒ Yes, How? w/ chlorine solution
☐ No, Why Not? _____
 Lab sample sent to for water quality analysis _____

Signature of Well Owner or Equitable Property Holder: _____
Heather Kissner
 Date: 2-7-2026

Please return White Copy to DANR Water Rights 523 E. Capitol Ave., Pierre SD 57501