

SOUTH DAKOTA WATER WELL COMPLETION REPORT

07-92


Location JW ¼ NW ¼ Sec 43-14-16 N 101 35 24 W
County Benet North T38NR
sec 28 36 W

Please mark well location with an "X"

43.2378 N
101.5900 W

Well Completion Date

3-16-24



LOCATION:

Distance from nearest potential pollution source (septic tank, abandoned well, feed lot, etc.)? _____ ft. from _____ (identify source).

PROPOSED USE:

☒ Domestic/Stock ☐ Municipal ☐ Business ☐ Test Holes
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Monitoring well

METHOD OF DRILLING:

Air Rotary

CASING DATA: ☐ Steel ☒ Plastic ☐ Other

If other describe _____

PIPEWEIGHT	DIAMETER	FROM	TO	HOLE DIAMETER
200 LB/FT	4 IN	0 FT	160 FT	8 IN
_____ LB/FT	_____ IN	_____ FT	_____ FT	_____ IN
_____ LB/FT	_____ IN	_____ FT	_____ FT	_____ IN

GROUTING DATA

Grout Type	No. of Sacks	Grout Weight	From	To
Wensel	7	60 lb./gal	10 ft	30 ft
_____	_____	_____ lb./gal	_____ ft	_____ ft

Describe grouting procedure Injected thru Tremie TubeSCREEN: ☐ Perforated pipe ☐ ManufacturedDiameter 4 IN Length 20 FEETMaterial SDR 21Slot Size .025 Set From 160 Feet to 200 Feet

Other information _____

WAS A PACKER OR SEAL USED? ☐ YES ☐ NO

If so, what material? _____

Describe packer(s) and location? _____

DISINFECTION: Was well disinfected upon completion?

☒ YES, How: _____☒ NO, Why Not? Owner Request
Circulated ChlorineLaboratory sent to for water
quality analysisWell Owner: Bob Shear

Business Name: _____

Address: Martin SD 57551

WELL LOG:

FORMATION	DEPTH	
	FROM	TO
Top Soil	0	1
blow Sand	1	20
SILT	20	60
Red Rock NCHALK ROCK	60	140
Sand Stone	140	200

STATIC WATER LEVEL 60 Feet

If flowing: closed in pressure _____ P:

GPM flow _____ through _____ inch pip

Controlled by ☐ Valve ☐ Reducers ☐ Other _____

Reduced Flowrate _____ GPM

Can well be completely shut in? _____

WELL TEST DATA:

☐ Pumped Describe: _____
☐ Bailed _____
☐ Other _____

Pumping Level Below Land Surface

_____ ft. After _____ Hrs. pumped _____ GPM

_____ ft. After _____ Hrs. pumped _____ GPM

If pump installed, pump rate _____ GPM

REMARKS

This well was drilled under license # 681

And this report is true and accurate.

Drilling firm Wild Goose Well Drilling

Signature of License Representative

Ehler Camp

Signature of Well Owner or Equitable Property Holder

RECEIVED

DEC 26 2024

OFFICE OF
WATER