


SOUTH DAKOTA WATER WELL COMPLETION REPORT

11-02

Location SW 1/4 SW 1/4 Sec 13 Twp 38N Rg 27WCounty TODD

North

Please mark well
location with an "X"

Well Completion Date

10-24-2024

Distance to nearest potential pollution source (septic tank, abandoned well, feed lot, etc.)?
ft. from N/A (identify source)

PROPOSED USE:

☒ Domestic/Stock ☐ Municipal ☐ Business ☐ Test holes
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Monitoring well

METHOD OF DRILLING:

ROTARY

CASING DATA:

☐ Steel ☒ Plastic ☐ Other

If other describe

PIPEWEIGHT	DIAMETER	FROM	TO	HOLE DIAMETER
200.0 LB/FT	4.00 IN	5.0 FT	0.0 FT	9.00 IN
200.0 LB/FT	4.00 IN	49.0 FT	5.0 FT	9.00 IN
200.0 LB/FT	4.00 IN	157.0 FT	149.0 FT	9.00 IN

GROUTING DATA:

Grout Type	No. of Sacks	Grout Weight	From	To
PORTLAND	7	94.6 Lb/gal	6.0 Ft	27.0 Ft

Describe grouting procedure

PUMPED

SCREEN:

☒ Perforated pipe ☐ Manufactured
Diameter 4.00 Inches Length 100.0 FeetMaterial PVCSlot Size .016 Set From 149.0 Feet to 49.0 FeetOther information SLOTTED WELL CASING

WAS A PACKER OR SEAL USED?

☐ Yes ☒ No

If so, what material?

Describe packer(s) and location

DISINFECTION: Was well disinfected upon completion?

☒ Yes, How? CHLORINATED
☐ No, Why Not?
Lab to which water
quality sample sent for analysisWell Owner: SCOTT ASSMAN

Business Name:

Address: 28636 283RD AVECity, State, Zip: MISSION SD 57555

WELL LOG:

FORMATION	DEPTH	
	FROM	TO
TOP SOIL	0	5
SOFT BED ROCK	5	59
HARD BED ROCK	59	98
SOFT BED ROCK	98	157

STATIC WATER LEVEL 51.0 FEET

If flowing: closed in pressure _____ PSI

GPM flow _____ through _____ Inch pipe

Controlled by ☐ Valve ☐ Reducers ☐ Other _____

Reduced flow rate _____ GPM

Can well be completely shut in?

WELL TEST DATA:

☒ Pumped Describe: SUBMERSIBLE
☐ Bailed
☐ Other

Pumping Level Below Land Surface

144.0 Ft. After 1.0 Hrs. pumped 20.0 GPM

_____ Ft. After _____ Hrs. pumped _____ GPM

If pump installed, pump rate: 22.0 GPM

REMARKS

2-390
 22 SQE 220
 N 43° 15' 35.64" W -100° 28' 15.41"

RECEIVED

JAN 27 2025

OFFICE OF
WATERThis well was drilled under license # 108 and this
report is true and accurate.Drilling firm: REIMERS WELL DRILLING LLC

Signature of License Representative:

Signature of Well Owner or Equitable Property Holder:

Date: 1-15-25