

SOUTH DAKOTA WATER WELL COMPLETION REPORT

2024

Location SW $\frac{1}{4}$ NW $\frac{1}{4}$ Sec 16 Twp 114N Rg 50W

County


DEUEL

GPS Coordinates

Lat: _____

Lon: _____

North

Please mark well location
with an "X" on section grid

Well Completion Date

11/4/2025

1 Mile

Distance from nearest potential pollution source (Septic tank, abandoned well, feed lot, etc.)

? 170 ft. from septic tank (identify source)

PROPOSED USE:

- ☒ Domestic/Stock ☐ Municipal ☐ Business ☐ Monitoring Well
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Test Hole
☐ Dewatering Well ☐ Geothermal ☐ Other _____

METHOD OF DRILLING: foward rotaryCASING DATA: ☐ Steel ☒ Plastic ☐ Other

If other describe _____

PIPEWEIGHT	DIAMETER	FROM	TO	HOLE DIAMETER
2dr21 LB/FT	5 IN	0 FT	43 FT	83/4 IN
LB/FT	IN	FT	FT	IN
LB/FT	IN	FT	FT	IN

GROUTING DATA:

Grout Type	No. of Sacks	Grout Weight	From	To
bent high solid	3	Lb/gal	0.0 Ft	Ft
		Lb/gal	Ft	Ft

Describe grouting procedure _____

SCREEN: ☐ Perforated pipe ☐ ManufacturedDiameter 5 Inches Length 10.0 FeetMaterial PVCSlot Size 5 Set From 33.0 Feet to 43.0 Feet

Other information _____

WAS A PACKER OR SEAL USED? ☐ Yes ☒ No

If so, what material? _____

Describe packer(s) and location _____

DISINFECTION: Was well disinfected upon completion?

☒ Yes, How? bleach☐ No, Why Not? _____Lab sample sent to for
water quality analysisWell Owner: Dan McKay

Business Name: _____

Address: 18637 469 avenueCity, State, Zip: Clear Lake, SD 57226

RECEIVED

MAY 13 2026

OFFICE OF
WATER

WELL LOG:

FORMATION	DEPTH	
	FROM	TO
topsoil	0.0	2.0
Brown clay	2.0	7.0
coarse sand	7.0	20.0
pearock	20.0	42.0

STATIC WATER LEVEL 8.0 FEET

If flowing: closed in pressure _____ PSI

GPM flow _____ through _____ Inch pipe

Controlled by ☐ Valve ☐ Reducers ☐ Other _____

Reduced flow rate _____ GPM

Can well be completely shut in? _____

WELL TEST DATA:

☐ Pumped Describe: _____☐ Bailed ☐ Air☐ Other _____

Pumping Level Below Land Surface

10.0 Ft. After 4.0 Hrs. pumped 75.0 GPM

_____ Ft. After _____ Hrs. pumped _____ GPM

If pump installed, pump rate: _____ GPM

REMARKS

This well was drilled under license # 480

And this report is true and accurate.

Drilling firm: Triiple S Construction/jerry wieber rep

Signature of License Representative:

Signature of Well Owner or Equitable Property Holder:

Date: 2/20/26

Please return White Copy to DANR Water Rights 523 E. Capitol Ave., Pierre SD 57501