


State 2nd Test Hole

SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

11-02

Location $\frac{1}{4}$ $\frac{1}{4}$ Sec Twp Rg County Please mark well
location with
an "X"Plugging Completion Date 3-30-26

Well Owner:

Name:

Stone Group Architects

Address:

600 East 7th St

City, State, Zip:

Sioux Falls S.D 57103

Comments:

Located in the NE 1/4 Section 19-T102N-R48W in Minnehaha County

EXISTING WELL ☐TEST HOLE ☒

Well depth

Casing material

Casing size(s)

Casing condition

Hole depth

Hole size

0-5 Top Soil
5-63 Yellow clay
63-109 black Rock
109-140 Sandstone
140' Granite
-142

Describe plugging procedure:

Run triemix line bottom of Test Hole - Pump or draw to top of Test Hole

Describe grout or plugging material:

Type of non-slip plug:

This well or test hole was plugged under license # 439 and this report is true and accurate.

Drilling firm:

Dave Putzke well Drilling & repair, Inc

Signature of Licensed Representative:

Dave Putzke

Signature of Well Owner:

Date:

RECEIVED

APR 07 2026

OFFICE OF
WATER