

state 1ST Test Hole


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

11-02

Location 1/4 1/4 Sec Twp Rg

County

Please mark well location with an "X"



Well Owner:

Name: Stone Group Architects

Address: 600 East 7th St

City, State, Zip: Sioux Falls S.D 57103

Comments:

Plugging Completion Date 3-26-26

Located in the NE 1/4 Section 19-T102N-R48W in Minnehaha County

EXISTING WELL ☐	TEST HOLE ☒
Well depth <u> </u>	Hole depth <u>204</u>
Casing material <u> </u>	Hole size <u>4 3/4</u>
Casing size(s) <u> </u>	0-5' T Soil
Casing condition <u> </u>	5-13' Fine sand
	13-30' brown clay
	30-54' Blue clay
	54-60' Sand & Gravel
	60-138' blue clay
	138-182' black rock
	182-204' Sandstone
	204' Granite

Describe plugging procedure:

Run tri-mix line bottom of Test Hole - pump DF Grout to top of Test Hole

Describe grout or plugging material:

Type of non-slip plug:

This well or test hole was plugged under license # 439 and this report is true and accurate.

Drilling firm: Dave Putke Well Drilling & Repair, Inc.

Signature of Licensed Representative: Dave Putke

Signature of Well Owner:

Date:

RECEIVED

APR 07 2026

OFFICE OF
WATER