


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NE 1/4 SE 1/4 Sec 6 Twp 122 Rg 64+63W

Well Owner:

County
BrownPlease mark well
location with
an "X"Name Paul LarsonAddress 13654 389th AveAberdeen SD 57401Plugging completion Date 8-26-25

RECEIVED

JAN 06 2026

OFFICE OF
WATER

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE



Well depth

1196

Casing material

Iron

Casing size(s)

2"

Casing condition

Poor

Hole depth

Hole size

Describe plugging procedure:

Pump Cement through pipe From Bottom up

Describe grout or plugging material:

20-94LB Bags Portland Cement mixed with 6 Gal WaterPer Bag

Type of non-slip plug:

This well or test hole was plugged under license # 209 And this report is true and accurate.Drilling firm Lenius Well Drilling

Signature of Licensed Representative

Brig Lenius

Signature of Well Owner

Paul Larson

Date

September 3, 2025