


SOUTH DAKOTA WELL AND TEST HOLE PLUGGING REPORT

10-85

Location NE 1/4 NW 1/4 Sec 12 Twp 125 Rg 64

County

BrownPlease mark well
location with
an "X"

Well Owner:

Name Journey ConstructionAddress 4500 W 58th StSioux Falls SD 57108Plugging completion Date 4-18-2025

CHECK APPROPRIATE BOX

EXISTING WELL



TEST HOLE



Well depth

1300 Ft.

Casing material

Copper

Casing size(s)

3"

Casing condition

Good

Hole depth

Hole size

RECEIVED

APR 24 2025

OFFICE OF
WATERDescribe plugging procedure: Blocked pump to top of the well, forced Cement Slurry
down the well.Describe grout or plugging material: 94 bags Cement mixed 5.7 gal of ^{water} per bag
of cementType of non-slip plug: Neat portland CementThis well or test hole was plugged under license # 440 And this report is true and accurate.

Drilling firm

Pullman Well Drilling

Signature of Licensed Representative

Cathy Rile

Signature of Well Owner

Date

4-18-25